



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 13, 2019 3:52:55 PM MST
Server Receive Date:	Dec 13, 2019 3:53:05 PM MST
Reference Number:	20191213-18126295187
Location:	15731 US-550, Bloomfield, NM 87413, USA Dec 13, 2019 3:48:09 PM MST [ <a href="#">View Map</a> ]

Information

Name	l.guerrero@kosinm.com
Date	Sep 18, 2019
Well Name	DUNKEL,ELMER GAS UNIT A 2
API Number	50670900200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soils

Photo of second corrective action completed



Completed work description of corrective action 2

Installed muffler box

Completed work description of corrective action 3

.

Completed work description of corrective action 4  
Summary of all work completed

.  
Cleaned up stained soils and installed muffler box to catch fluids from muffler.