



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 15, 2019 4:20:34 PM MST
Server Receive Date:	Dec 15, 2019 4:20:42 PM MST
Reference Number:	20191215-18126480868
Location:	13 Road 51921, Bloomfield, NM 87413, USA Dec 15, 2019 4:19:26 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Sep 30, 2019
Well Name	PAYNE, EVELYN GAS UNIT C 2
API Number	50670694900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Installed silt trap with rock run downs and silt bowls

Photo of second corrective action completed



Completed work description of corrective action 2

Installed diversion berm to divert storm water away from equipment

Photo of third corrective action completed



Completed work description of corrective action 3

Installed silt trap with rock run downs

Completed work description of corrective action 4

.

Summary of all work completed

Installed silt traps with rock armored run downs.
Installed berm to divert storm water from equipment.
Removed all trash and debris.