



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 15, 2019 4:52:11 PM MST
Server Receive Date:	Dec 15, 2019 4:52:17 PM MST
Reference Number:	20191215-18126483342
Location:	13 Road 51921, Bloomfield, NM 87413, USA
	Dec 15, 2019 4:49:24 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Sep 26, 2019
Well Name	PAYNE, EVELYN GAS UNIT A 1
API Number	50670677800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Created diversion ditch to divert storm water to rock armored run downs.

Photo of second corrective action completed



Completed work description of corrective action 2

Completed work description of corrective action 3

Completed work description of corrective action 4

Summary of all work completed

Cleaned up stained soils.

.

.

Created diversion ditch to divert storm water into
rock armored run downs. Cleaned up stained soils.
Removed all trash and debris from location.