



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 26, 2019 5:11:04 PM MST
Server Receive Date:	Dec 26, 2019 5:11:10 PM MST
Reference Number:	20191227-18127820233
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Dec 26, 2019 5:10:07 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 23, 2019
Location Name (Other)	Pine River 2-29 #2
API Number	50670648300
Select State	Colorado
Work type	COGCC Inspection AR

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Removed unused catwalk by wellhead.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

Installed rock armored run down on erosion channel.



Completed work description of corrective action 4

Created diversion ditch on western side of pad and installed rock armored run down.

Additional photos



Summary of all work completed

Removed unused catwalk by the wellhead. Installed rock armored run downs with diversion ditches.