

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402067063

Receive Date:

12/30/2019

Report taken by:

ROB YOUNG

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: FRITZLER RESOURCES INC	Operator No: 31257	Phone Numbers
Address: P O BOX 114		Phone: (970) 8679388
City: FORT MORGAN State: CO Zip: 80701		Mobile: (970) 7680845
Contact Person: Gene Fritzler	Email: gfritzler12@gmail.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 9401 Initial Form 27 Document #: 2144738

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input checked="" type="checkbox"/> Other SKIM PIT REPLACEMENT |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: PIT	Facility ID: 107652	API #:	County Name: WASHINGTON
Facility Name: JOLLY	Latitude: 39.793154	Longitude: -103.576838	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NENE	Sec: 18	Twp: 3S	Range: 55W Meridian: 6 Sensitive Area? No

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use PASTURE

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

N/A

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☐ E&P Waste

☒ Other E&P Waste

☐ Non-E&P Waste

☐ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☒ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
	SOILS	TBD	ANALYSIS TO BE PERFORMED: TPH, BTEX

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures taken to abate, investigate, and/or remediate impacts associated with E&P Waste.

SKIM PIT Was REMOVED FROM SERVICE. A Skim Tank was installed

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Landfarming was not attempted . The soils were excavated from the pit and disposed of at a waste management facility
Sampling of the pit was completed in December 2018. Results are presented in attachments

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6

Number of soil samples exceeding 910-1 4

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 400

NA / ND

-- Highest concentration of TPH (mg/kg) 24

-- Highest concentration of SAR 14.3

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 8

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

SIDES AND BOTTOMS OF PIT WILL BE EXCAVATED.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

The sides and bottom of the skim pit were excavated and transported off-site to a waste management site. Analytical data currently shows the soil SAR values are slightly above the SAR value of 12. The values are at depths greater than 3 ft. NO revegetation is required. Since the Skim pit is surrounded by the evaporation pits, further excavation would breach the sidewalls.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) _____ 108
Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

N/A

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other December 2019 Project Status

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

The skim pit was excavated and soils were transported to Waste Management Denver Arapahoe Disposal
111 tons or 108 cu yds were disposed. A copy of manifest tickets is attached

Volume of E&P Waste (solid) in cubic yards _____ 108

E&P waste (solid) description _____ Excavated soils from skim pit

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Waste Management Denver
Arapahoe Disposal

Volume of E&P Waste (liquid) in barrels _____ 65

E&P waste (liquid) description _____ Mud and Tank Bottoms

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: NGL Waater Solutions , DJ, LLC

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes _____

Do all soils meet Table 910-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

RECLAMATION OF PIT WILL REQUIRE EXCAVATION, SOIL ANALYSIS, BACKFILL AND COMPACTION. THE AMOUNT OF BACKFILL WILL BE CONTINGENT ON QUANTITY OF SOILS SENT TO THE DISPOSAL FACILITY. THE SITE INVESTIGATION INCORPORATES EXCAVATION AND SAMPLING. EXCAVATION OF E&P WASTE FROM THE PIT WILL BE COMPLETED UPON RECEIPT OF ACCEPTABLE ANALYTICAL RESULTS. A TPH TEST KIT WILL BE USED PRIOR TO SENDING CONFIRMATION SAMPLES IN FOR ANALYSIS. COMPOSITE SAMPLES FROM EACH SIDE AND THE BOTTOM, (5 TOTAL) WILL BE EVALUATED FOR THE CONSTITUENTS PREVIOUSLY DISCUSSED.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☒ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/15/2015

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. 12/05/2018

REMEDIAL ACTION DATES

Date of commencement of Remediation. 11/28/2018

Date of completion of Remediation. 12/05/2018

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

As requested, copies of manifest tickets are attached.
The legacy skim pit was closed,
A perimeter trench was placed around the exiting pits .
Berms have been improved and a road into #2 with proper drainagie was constructed

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Gene Fritzler

Title: vp

Submit Date: ` 12/30/2019

Email: gfritzler12@gmail.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: ROB YOUNG

Date: 01/07/2020

Remediation Project Number: 9401

COA Type**Description**

	Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.
--	---

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402067063	FORM 27-SUPPLEMENTAL-SUBMITTED
402067070	DISPOSAL MANIFESTS

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)