

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> BROZOVICH 1-8	<b>Facility ID:</b> 114338
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> EXTRACTION OIL & GAS INC / 10459	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> BROZOVICH #MA 8-8J (API 05-001-08812, Facility ID 203303, Loc ID 321503) *well name was changed 1995	

<b>County:</b> ADAMS			
<b>Township:</b> 1S	<b>Range:</b> 68W	<b>Section:</b> 8	<b>QQ:</b> SENE
<b>Original Latitude/ Longitude:</b>		/	
<b>Updated Latitude/ Longitude:</b> 39.980881		/ -105.01828	
<b>Basis for Location Change:</b>			
Pit was located in wrong section (was 9, should be 8). Location corrected and lat/long moved to TB (aerial imagery)			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                   | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664637           | Date: 2/7/1989   |
|                                     | Doc #: 321939                                 | Date: 12/17/1992 |
|                                     | Doc #: 321913                                 | Date: 9/26/1997  |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:     | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                 | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                       | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                        | Date:            |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 114337 |                  |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached)   |                  |
| <input type="checkbox"/>            | Other:  |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; field inspections document a concrete produced water vault on location. Pit status has been changed to Closed.

