


Inspection Photos
Location Name:Beisel 42-1
Location ID: 320427



Photo#1 Production tank and Produced Water Tank

Photo#2 Separator/Gas Meter

Inspection Photos
Location Name: Beisel 42-1
Location ID: 320427



Photo#3 Corrective Action: Gas Meter needs calibrated

Photo#4 Wellhead

Inspection Photos
Location Name:Beisel 42-1
Location ID: 320427



Photo#5 Corrective Action:Stained Soil needs Cleaned Up