

Inspection Photos
Location Name: Triangle 6-22
Location ID: 432327



Colorado Oil and Gas Conservation Commission
40.56223, -104.64988, 1457.8m, 193°
Jan 7, 2020 14:09:39

Photo 1: Tank Battery Signs



Colorado Oil and Gas Conservation Commission
40.56219, -104.65005, 1454.0m, 91°
Jan 7, 2020 14:11:16

Photo 2: Tank Battery

Inspection Photos
Location Name: Triangle 6-22
Location ID: 432327



Photo 3: Unused riser



Photo 4: Not labeled as "future use"

Inspection Photos
Location Name: Triangle 6-22
Location ID: 432327



Photo 5: Unused riser



Photo 6: Not labeled for "future Use"



Inspection Photos
Location Name: Triangle 6-22
Location ID: 432327



Photo 7: Unused riser. (LO/TO)



Photo 8: Unused Riser (LO/TO)