

Inspection Photos

Location Name: MARMOT 41-2 CA DATE 1-7-20

API#: 05-071-06676

INSP. #: 695101962



Colorado Oil & Gas Conservation Commission
37.11661, -104.74141, 1970.0m, 288°
2020/01/07 11:28:41

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.11699, -104.74136, 1983.0m, 65°
2020/01/07 11:30:05

PHOTO 2: WELL SIGN




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MARMOT 41-2 CA DATE 1-7-20

API#: 05-071-06676

INSP. #: 695101962



**PHOTO 3: FLUID LEVEL IN PIT IS ABOVE 2' FREEBOARD
MARKER (SPOKE WITH JACK WISEMAN BY PHONE APP. 11:40
1-7-20). MAINTAIN AT LEAST 2' FREEBOARD IN PIT PER RULE
902.b. CA DATE 1-8-20**