

Inspection Photos

1/06/2020

Operator: DIAMOND BACK DRILLING &
SUPPLY INC - 24120

Location ID: 398188

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398188



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Location currently covered in snow preventing Reclamation Specialist from conducting an accurate assessment of the reclamation. Follow-up inspection will be needed in a future growing season.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398188



Photo 3: See comments under photo 1. Photo also shows pit and excavated soils on the north end of the Location.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398188



Photo 5: Photo taken from the location. Photo shows cable anchor remaining on location.