

# Inspection Photos

1/06/2020

Operator: D & D RESOURCES INC - 22315

Location ID: 315632

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

**Inspection Photos**  
**Operator Name: D & D RESOURCES INC - 22315**  
**Location ID: 315632**



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Location currently covered in snow preventing Reclamation Specialist from conducting an accurate assessment of the reclamation. Follow-up inspection will be needed in a future growing season.



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: D & D RESOURCES INC - 22315  
Location ID: 315632



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.