

Inspection Photos

1/06/2020

Operator: DIAMOND BACK DRILLING &

SUPPLY INC - 24120

Location ID: 398240

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398240



Photo 1: Photo taken from the west end of the Location facing northeast. Photo provides an overview of the Location.



Photo 2: Photo taken from the west end of the Location facing east. Photo provides an overview of the Location.

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398240



Photo 3: Photo taken from the east end of the Location. Photo shows cable debris/equipment remaining on the Location.



Photo 4: Photo of GPS verifying Location.

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398240



Photo 5: Photo taken from the south end of the Location, facing southwest. Photo shows what appears to be a pit.



Photo 6: Photo taken from the south end of the Location, facing north. Photo shows what appears to be a pit.