

Inspection Photos

1/06/2020

Operator: D & D RESOURCES INC - 22315

Location ID: 315492

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315492



Photo 1: Photo taken from the south end of the Location, facing north. Photo shows overview of the Location; no well marker exists on this Location.



Photo 2: Photo taken from the south end of the Location, facing east. Photo shows utility pole/equipment remaining on the Location.

Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315492



Photo 3: Photo taken from the north end of the Location, facing southeast. Photo shows overview of the Location. No well marker exists on this Location.



Photo 4: Photo taken from the north end of the Location, facing southwest. Photo shows overview of the Location. No well marker exists on this Location. Photo also shows utility pole/equipment remaining on Location (yellow arrow) see photo 2). Note: Pole is not connected to the line that runs left to right in the photo (red arrow).