

Inspection Photos
Location Name: Pronghorn K-5-8XRLNB
Location ID: 438694



Colorado Oil and Gas Conservation Commission
40.43684, -104.23182, 4611.3ft, 274°
01/07/2020 11:37:20

Photo 1 – Pumping Unit



Colorado Oil and Gas Conservation Commission
40.43737, -104.23226, 4599.7ft, 199°
01/07/2020 11:38:26

Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Pronghorn K-5-8XRLNB
Location ID: 438694




Photo 3 – Check valve is leaking causing stained soil.

