

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402279759

Date Received:

01/08/2020

Spill report taken by:

Graber, Candice
(Nikki)

Spill/Release Point ID:

470543

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1001 NOBLE ENERGY WAY</u>		Phone: <u>(970) 3045014</u>
City: <u>HOUSTON</u>	State: <u>TX</u>	Mobile: <u>(970) 2034238</u>
Zip: <u>77070</u>		Email: <u>howard.aamold@nblenergy.com</u>
Contact Person: <u>Howard Aamold</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402277459

Initial Report Date: 01/06/2020 Date of Discovery: 01/05/2020 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 15 TWP 7N RNG 64W MERIDIAN 6

Latitude: 40.566460 Longitude: -104.526261

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY
☒ Facility/Location ID No 436519
Spill/Release Point Name: Furrow USX AB
☐ No Existing Facility or Location ID No.
Number: 15-99HZ
☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Sunny 40 degreesSurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Oil transport operator experienced an unintentional release of 5 barrels of oil during fluid transfer operations at the Furrow USX AB 15-99HZ Battery. Release was outside containment, cleanup is under way.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
1/5/2020	COGCC	Nikki Graber	-	
1/5/2020	Weld County	Jason Maxey	-	
1/5/2020	Weld County	Roy Rudisill	-	
1/5/2020	Noble Land	Land Owner	-	

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/08/2020		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	5	5	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, including walls & floor regardless of construction material , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
The extent of impacts will be determined through excavation of impacted soil above COGCC Table 910-1 standards. A third party environmental consultant will collect grab soil samples and transport them to a certified laboratory under proper chain of custody procedures for analysis of TPH-DRO, TPH-GRO, BTEX, and Naphthalene, pH, SAR, and EC			
Soil/Geology Description:			
Road base			

Number Water Wells within 1/2 mile radius: 0

Water Well	3448	None	<input type="checkbox"/>
------------	------	------	--------------------------

Surface Water	3539	None	
---------------	------	------	---

None ☒

Occupied Building 3473 None

No additional spill details

Form 27 Remediation Project No:

Title: Environmental Coordinator Date: 01/08/2020 Email: howard.aamold@nblenergy.com

Description

Name

Comment Date

Total: 0 comment(s)