

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402280055

Date Received:  
01/08/2020

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Jessica Dooling

970-675-4122

jessica\_dooling@xtoenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 679706829

Inspection Date: 01/06/2020

FIR Submit Date: 01/07/2020

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

### LOCATION - Location ID: 316338

Location Name: LITTLE HILLS FEDERAL-61N97W Number: 35NWNE County: RIO BLANCO

Qtrqtr: NWNE Sec: 35 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.015760 Longitude: -108.244800

### FACILITY - API Number: 05-103-00 Facility ID: 267008

Facility Name: LITTLE HILLS FEDERAL Number: F31X-35G

Qtrqtr: NWNE Sec: 35 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.015760 Longitude: -108.244800

### CORRECTIVE ACTIONS:

1 ☒ CA# 135720

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/08/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: The venting gas was the result of a frozen needle valve. It was fixed on 1/6/2020 at 8PM. The well is checked at regular intervals.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA completed on 1/6/2020 at 8PM. The venting gas was the result of a frozen needle valve. It was fixed on 1/6/2020 at 8PM. The well is checked at regulatr intervals.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: \_\_\_\_\_

Title: Regulatory Coordinator

Date: 1/8/2020 11:17:43 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

402280055	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files