

Inspection Photos

API: 05-071-09503

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/9/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09503 | Date: 1/9/2020

Inspection Photos



Photo 1. Facing northwest toward the location. There are numerous noxious weeds that are present at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09503 | Date: 1/9/2020

Inspection Photos



Photo 2. Facing south toward the location. There are numerous Plumeless thistle at the location which were not controlled since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09503 | Date: 1/9/2020

Inspection Photos



Photo 4. Facing south from the roadway. The noxious weeds have spread offsite northeast of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-09503 | Date: 1/9/2020