

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2020

Submitted Date:

01/10/2020

Document Number:

689704001

FIELD INSPECTION FORM
 Loc ID: 414231
 Inspector Name: LONGWORTH, MIKE
 On-Site Inspection: ☐
 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414193	WELL	XX	01/31/2019	LO	045-18801	NPR 12A-3-696	DG
414194	WELL	XX	01/31/2019	LO	045-18800	NPR 12B-3-696	DG
414196	WELL	XX	01/31/2019	LO	045-18798	NPR 15B-3-696	DG
414197	WELL	XX	01/31/2019	LO	045-18797	NPR 15C-3-696	DG
414198	WELL	XX	01/31/2019	LO	045-18796	NPR 21B-9-696	DG
414199	WELL	XX	01/31/2019	LO	045-18795	NPR 12C-3-696	DG
414200	WELL	XX	01/31/2019	LO	045-18802	NPR 12D-3-696	DG
414201	WELL	XX	01/31/2019	LO	045-18794	NPR 13B-3-696	DG
414202	WELL	XX	01/31/2019	LO	045-18803	NPR 13C-3-696	DG
414203	WELL	XX	01/31/2019	LO	045-18793	NPR 13D-3-696	DG
414204	WELL	XX	01/31/2019	LO	045-18804	NPR 14A-3-696	DG
414206	WELL	XX	01/31/2019	LO	045-18805	NPR 14D-3-696	DG
414207	WELL	XX	01/31/2019	LO	045-18806	NPR 15A-3-696	DG
414208	WELL	XX	01/31/2019	LO	045-18807	NPR 23D-4-696	DG
414209	WELL	XX	01/31/2019	LO	045-18813	NPR 24B-4-696	DG
414210	WELL	XX	01/31/2019	LO	045-18808	NPR 25A-4-696	DG
414211	WELL	XX	01/31/2019	LO	045-18814	NPR 25C-4-696	DG
414212	WELL	XX	01/31/2019	LO	045-18809	NPR 14B-3-696	DG
414213	WELL	XX	01/31/2019	LO	045-18815	NPR 14C-3-696	DG

414214	WELL	XX	01/31/2019	LO	045-18810	NPR 25D-4-696	DG
414220	WELL	XX	01/31/2019	LO	045-18819	NPR 15D-3-696	DG
414221	WELL	XX	01/31/2019	LO	045-18820	NPR 16A-3-696	DG

General Comment:

This is a summary of inspection report.

On Friday 01/10/2020 at approximately 1130 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC NPR 004-696 Pad, at Location # 414231 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

No Location Signage.

Install sign to comply with Rule 305.g.

C.A. Date 02/11/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Construction along access road. Running pipe lines from location.		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	No Location Signage.		
Corrective Action:	Install sign to comply with Rule 305.g.	Date:	02/11/2020

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>414193</u>	Type: <u>WELL</u>	API Number: <u>045-18801</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414194</u>	Type: <u>WELL</u>	API Number: <u>045-18800</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414196</u>	Type: <u>WELL</u>	API Number: <u>045-18798</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414197</u>	Type: <u>WELL</u>	API Number: <u>045-18797</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414198</u>	Type: <u>WELL</u>	API Number: <u>045-18796</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414199</u>	Type: <u>WELL</u>	API Number: <u>045-18795</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414200</u>	Type: <u>WELL</u>	API Number: <u>045-18802</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414201</u>	Type: <u>WELL</u>	API Number: <u>045-18794</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414202</u>	Type: <u>WELL</u>	API Number: <u>045-18803</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414203</u>	Type: <u>WELL</u>	API Number: <u>045-18793</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414204</u>	Type: <u>WELL</u>	API Number: <u>045-18804</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414206</u>	Type: <u>WELL</u>	API Number: <u>045-18805</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414207</u>	Type: <u>WELL</u>	API Number: <u>045-18806</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414208</u>	Type: <u>WELL</u>	API Number: <u>045-18807</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414209</u>	Type: <u>WELL</u>	API Number: <u>045-18813</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414210</u>	Type: <u>WELL</u>	API Number: <u>045-18808</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414211</u>	Type: <u>WELL</u>	API Number: <u>045-18814</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414212</u>	Type: <u>WELL</u>	API Number: <u>045-18809</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>414213</u>	Type: <u>WELL</u>	API Number: <u>045-18815</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>

Facility ID:	414214	Type:	WELL	API Number:	045-18810	Status:	XX	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Facility ID:	414220	Type:	WELL	API Number:	045-18819	Status:	XX	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Facility ID:	414221	Type:	WELL	API Number:	045-18820	Status:	XX	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Well Drilling

Rig: Rig Name: KLA Drilling Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Drilling conductor.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704002	Inspection 689704001 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034745