

# *Inspection Photos*

*Loc#334618*

*Operator: Caerus*

*Inspection Number: 692401783*

*Inspection Date: 1/9/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southeast.

January 9,2020



Photo#2:  
Open Cellar.



Photo#3:  
Open Cellar; Venting Well.

January 9, 2020



Photo#4:  
View of Interim Area.

January 9, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#5:  
View of Interim Area.

Caerus HMU Fed Loc#334618