

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 335312



Dump line running in trench to tank battery

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 335312



Sales line locked out and tagged out



Stainless steel to replace old Dump line