

Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW

Location ID: 334074



Photo #0392 photo from entrance to location.




Photo #0393 Multiple holes in tank containment liner.