


Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Production facility



Wellhead

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash



Trash and pipe

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash



Trash

Inspection Photos
Location Name: Phelps 1-13
Location ID: 319627



Trash