

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

699100903

FIELD INSPECTION FORMLoc ID 425450 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425451	WELL	PA	02/17/2016	GW	123-34390	OSTER C19-27D	PA
425452	WELL	PR	10/01/2019	GW	123-34391	NEI C17-33D	PR
425453	WELL	PR	10/01/2019	GW	123-34392	NEI C18-24D	PR
425454	WELL	PR	03/01/2019	OW	123-34393	NEI C18-23D	PR
425455	WELL	PR	10/01/2019	GW	123-34394	NEI C18-32D	PR
425456	WELL	PR	10/01/2019	GW	123-34395	NEI C18-33D	PR
425457	WELL	PR	10/01/2019	GW	123-34396	NEI C18-21D	PR
425462	WELL	PR	10/01/2019	GW	123-34398	NEI PC C18-20D	PR
425463	WELL	PR	10/01/2019	GW	123-34399	NEI C18-22D	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash next to the meter run needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/23/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel X8		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	OTHER	BV CONCRETE		,	
Comment:	Shares Containment with crude oil tanks.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		40.311750,-104.596040	
Comment:						
Corrective Action:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Burns, Adam

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Concrete	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 425451 Type: WELL API Number: 123-34390 Status: PA Insp. Status: PA

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Plugged and Abandoned

Corrective Action: _____ Date: _____

Facility ID: 425452 Type: WELL API Number: 123-34391 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425453 Type: WELL API Number: 123-34392 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425454 Type: WELL API Number: 123-34393 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425455 Type: WELL API Number: 123-34394 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425456 Type: WELL API Number: 123-34395 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425457 Type: WELL API Number: 123-34396 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425462 Type: WELL API Number: 123-34398 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	PR		
Corrective Action:		Date:	
Facility ID: <u>425463</u> Type: <u>WELL</u> API Number: <u>123-34399</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	PR		
Corrective Action:		Date:	

<u>COGCC Comments</u>		
Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 1/14/20 at approximately 0847 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Oster C 19-27D Facility of Noble Energy, at Location ID: 425450 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Trash next to meter run needs to be removed for good housekeeping. See attached photos. Comply with Rule 603.f . With a corrective action date of 1/23/20 See attached photos A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing education inspections</p>	burnsa	01/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100904	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036969