

Inspection Photos  
Operator: BP America  
Location/API #: 067-08639  
Date: 1-9-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Perennial grasses such as crested wheatgrass is growing on berms.



Photo 4. View of the southern project area from the southwestern corner facing eastward. Musk thistles are observed here.



Photo 5. View of reference area, comprised of sagebrush shrubland.