

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-07861**  
**Date: 1-9-2020**



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the project area from the northern corner facing southeastward. Musk thistles observed above the snow.



Photo 3. View of reference area vegetation (in background), comprised of irrigated field that is largely snow covered at this time.