

Inspection Photos
Location Name: Rainbow LC28-74 PAD
Location ID: 422406



Photo 1 – Ptasnik LC 28-76HN



Photo 2 – Ptasnik LC 28-76HN Tank Battery



Inspection Photos
Location Name: Rainbow LC28-74 PAD
Location ID: 422406



Photo 3 – Middle East Pad



Photo 4 – West Pad

Inspection Photos
Location Name: Rainbow LC28-74 PAD
Location ID: 422406



Photo 5 – Tank Battery



Photo 6 – Produced Water Tanks

Inspection Photos
Location Name: Rainbow LC28-74 PAD
Location ID: 422406



Photo 7 – Separators



**Photo 8 – Unused Sand Trap on the South side of location,
near Main Lease Road.**

Inspection Photos
Location Name: Rainbow LC28-74 PAD
Location ID: 422406



Photo 9 – Unused Equipment on the North side of location, west of Methanol Day Tank.



Photo 10 – Unused Equipment on the North side of location, west of Methanol Day Tank.