

Inspection Photos  
Location Name: HSR-Vogl 5-8A  
Location ID: 330917





Photo 1 WH sign

Photo 2 WH

**Inspection Photos**  
**Location Name: HSR-Vogl 5-8A**  
**Location ID: 330917**



**Photo 3 Stained soil around bradenhead**

**Photo 4 possible leak from WH valve**