

Inspection Photos
Location Name: Elk Springs Unit 3
Location ID: 311768



Photo 1. Overview of location taken facing east.



Photo 2. Equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elk Springs Unit 3
Location ID: 311768



Photo 3. Stained soil under pump jack.



Photo 4. No secondary containment.