

Inspection Photos
Location Name: Babb 15-14
Location ID: 327704



Photo 1: View of oily waste stockpiled on liner at former tank battery, looking east.



Photo2: View of oily waste stockpiled on liner at former tank battery, looking south.

Inspection Photos
Location Name: Babb 15-14
Location ID: 327704




Photo 3: Debris at former tank battery



Photo 4: View at wellpad, looking southwest. T-post is likely well location.

Inspection Photos
Location Name: Babb 15-14
Location ID: 327704



Picture: Aerial image of 2009 aerial, showing former well pad, tank battery and pit location.

