

Location Name: – Kloefkorn Tank Battery – Rem #10741  
Inspection Date: 12/11/2019



Photo # 1 – View east across partially backfilled former oil skim pit (119716)

Location Name: – Kloefkorn Tank Battery – Rem #10741  
Inspection Date: 12/11/2019



Photo # 2 – View north at clean backfill stockpile and former land treatment area in background