

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-09504**  
**Date: 1-15-2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with grasses such as intermediate wheatgrass and crested wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of erosional channel, approximately 1 foot wide and deep observed within the northern project area.



Photo 5. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.