

Pressure Test Inspection

Total Records: 14



Location Name: E20E

Line Name	Test Date	Representative	Start Pressure (psi)	End Pressure (psi)	Start Time	End Time	Duration	Test Result
DUMPLINE TO TANK #81663 AND #81664	2019-08-14	Jeremiah Crawford	246	246	12:00:00	12:30:00	00:30:00	Pass
SALES LINE	2019-08-14	Jeremiah Crawford	121	119	12:00:00	12:30:00	00:30:00	Pass
Shideler 20-5 (E20E)	2019-08-14	Jeremiah Crawford	206	206	12:00:00	12:30:00	00:30:00	Pass
Shideler Federal 20-3 (E20E)	2019-08-14	Jeremiah Crawford	250	250	12:00:00	12:30:00	00:30:00	Pass
Shideler Federal 20-4 (E20E)	2019-08-14	Jeremiah Crawford	246	246	12:00:00	12:30:00	00:30:00	Pass
2IN DUMP LINES	2019-12-12	Jeremiah Crawford	250	249	14:30:00	15:00:00	00:30:00	Pass
3IN SALES LINE	2019-12-12	Jeremiah Crawford	200	197	13:50:00	14:20:00	00:30:00	Pass
TANK #81663	2019-12-12	Jeremiah Crawford	250	249	14:30:00	15:00:00	00:30:00	Pass
TANK #81664	2019-12-12	Jeremiah Crawford	250	249	14:30:00	15:00:00	00:30:00	Pass
DUMPLINE TO TANKS	2020-01-09	Jeremiah Crawford	398	398	09:10:00	09:40:00	12:30:00 AM	Pass
SALES LINE	2020-01-09	Jeremiah Crawford	135	135	09:10:00	09:40:00	12:30:00 AM	Pass
Shideler 20-5 (E20E)	2020-01-09	Jeremiah Crawford	422	421	09:10:00	09:40:00	12:30:00 AM	Pass
Shideler Federal 20-3 (E20E)	2020-01-09	Jeremiah Crawford	507	507	09:10:00	09:40:00	12:30:00 AM	Pass
Shideler Federal 20-4 (E20E)	2020-01-09	Jeremiah Crawford	398	398	09:10:00	09:40:00	12:30:00 AM	Pass

Notes

Pressure test sales line and dumplines after repair to sales line leak.

12/12/2019 12:00:00 AM