

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06559**  
**Date: 1-15-2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Based on operator submitted documentation, re-seeding was conducted in 2018. As vegetation is in a dormant condition, germination and revegetation success should be assessed during the active 2020 growing season.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of Russian thistle debris within the southern project area.



Photo 5. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.