

Inspection Photos

Location Name: CUCUMBER 43-5 R

API#: 05-071-09064

INSP. #: 695102028



Colorado Oil & Gas Conservation Commission
37.28589, -104.9052, 2535.0m, 275°
2020/01/16 10:48:16



Colorado Oil & Gas Conservation Commission
37.28615, -104.90544, 2528.0m, 262°
2020/01/16 10:48:58

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: CUCUMBER 43-5 R CA DATE 2-16-20

API#: 05-071-09064

INSP. #: 695102028



PHOTO 3: UNUSED EQUIPMENT TWO 2" RISERS AND ONE 1" RISERS ON LOCATION. UNUSED RISERS ARE CONSIDERED UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT PER RULE 603.f. CA DATE 2-16-20