

Inspection Photos

Location Name: GROLSCH 44-7 CA DATE 2-16-20

API#: 05-071-07652

INSP. #: 695102034



Colorado Oil & Gas Conservation Commission
37.26606, -104.92243, 2378.0m, 31°
2020/01/16 12:10:50



Colorado Oil & Gas Conservation Commission
37.26623, -104.92207, 2399.0m, 142°
2020/01/16 12:11:22

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: GROLSCH 44-7 CA DATE 2-16-20

API#: 05-071-07652

INSP. #: 695102034



PHOTO 3: ARE OF IMPACTED SOIL APPEARS TO BE FROM LEAK HYDRAULIC CONNECTION OF DRIVEHEAD HOSE. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.