

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 1. Overview of location taken facing south.



Photo 2. No wellhead signs at wellhead.