

Inspection Photos

API: 05-017-07705

Operator: VECTA OIL & GAS

Inspection Date: 1/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07705 | Date: 1/14/2020

Inspection Photos



Photo 1. The area where the cattle existed is now fenced off. This area has accumulated sand and has filled in the cattle guard. Arrow points to the two cattle guard posts. The cattle guard will need to be removed and area reclaimed.
Lat/Long: 38.86674/-102.66708



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07705 | Date: 1/14/2020

Inspection Photos



Photo 2. Center of the location facing north. Native vegetation appears to be fully established.



Inspection Photos



Photo 3. Center of the location facing west. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-017-07705 | Date: 1/14/2020

Inspection Photos



Photo 4. Center of the location facing south. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07705 | Date: 1/14/2020

Inspection Photos



Photo 5. Center of the location facing east. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-017-07705 | Date: 1/14/2020