

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/16/2020

Submitted Date:

01/16/2020

Document Number:

697000402**FIELD INSPECTION FORM**
 Loc ID 321959 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 59925Name of Operator: MONUMENT GAS MARKETING INCAddress: P O BOX 950City: MONUMENT State: CO Zip: 80132-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Campbell, Randy	(719) 481-8029	rcampbell0614@adelphia.net	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285920	WELL	PR	01/31/2007	GW	017-07641	GLADYS COTRELL TRUST 2	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through CRP		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 4		
Comment:	Gas scrubber, solar powered cathodic rectifier, propane tanks, telemetry equipment at meter sheds		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 228		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Meter sheds on east side of location		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	350 Vortec Chevy motor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:	Separator on east side of tanks next to berms	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		38.692000,-102.541440

Comment:	East tank is 300bbl tank	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Date:	
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	STEEL AST		38.692000,-102.541440

Comment:	West tanks are 250bbl tanks	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	250bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shared berms	Date:	
Corrective Action:		Date:	

Venting:

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	

Inspected Facilities				
Facility ID: 285920	Type: WELL	API Number: 017-07641	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Production			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT