

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-08767
Date: 1-22-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern cut-slope facing eastward. Weeds remain and revegetation is not conducted.