



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 15, 2020 2:08:51 PM MST
Server Receive Date:	Jan 15, 2020 2:11:22 PM MST
Reference Number:	20200115-18129671187
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 15, 2020 2:11:04 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jan 15, 2020
Well Name	ROBERTSON GAS UNIT 19-01 1
Location Name (Other)	state com bz 2
API Number	50670665000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed



before mowing

Completed work description of corrective action 3
Photo of fourth corrective action completed



after mowing

Completed work description
Completed work description of corrective action 4

anchor marked
removed weed debris from around equipment and
reclamation area and addressed findings

Additional photos



Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

initial treatment 4/9/19

Summary of all work completed

addressed findings from inspection