



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 17, 2020 2:53:45 PM MST
Server Receive Date:	Jan 17, 2020 2:56:12 PM MST
Reference Number:	20200117-18129895853
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 17, 2020 2:53:16 PM MST [ <a href="#">View Map</a> ]

Information

Name	colen@horizonenvservices.com
Date	Jan 17, 2020
Well Name	MAGOON GAS UNIT D 1
API Number	50670832400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

removed unused valve and spool piece

Photo of second corrective action completed



Completed work description of corrective action 2

removed empty plastic lube oil tote

Completed work description of corrective action 3

removed unused equipment

Completed work description of corrective action 4  
Summary of all work completed

removed unused equipment  
removed unused equipment