



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 17, 2020 2:56:36 PM MST
Server Receive Date:	Jan 17, 2020 2:59:02 PM MST
Reference Number:	20200117-18129897571
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 17, 2020 2:58:56 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jan 17, 2020
Well Name	COWEN, GRACE GAS UNIT A 1
API Number	50670741800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

removed unused telemetry equipment, solar panel and jbox

Completed work description of corrective action 2

removed unused equipment

Completed work description of corrective action 3

removed unused equipment

Completed work description of corrective action 4

removed unused equipment

Summary of all work completed

removed unused equipment from location