



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Jan 17, 2020 3:59:49 PM MST
Server Receive Date: Jan 17, 2020 4:02:20 PM MST
Reference Number: 20200117-18129906300
Location: 557 Airpark Dr, Durango, CO 81303, USA
Jan 17, 2020 4:01:16 PM MST [[View Map](#)]

Information

Name: colen@horizonenvservices.com
Date: Jan 16, 2020
Location Name (Other): Anderson C2/C3
Location API (Other): 0506709886
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Clean Up Weed Debris
Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed stained soil and replaced gravel

Photo of third corrective action completed



Completed work description of corrective action 3

removed weed debris from around equipment and in reclamation area

Photo of fourth corrective action completed



Completed work description

replaced tank sign with new sign

Completed work description of corrective action 4

addressed inspection findings

Additional photos



Additional photos



Additional photos



Summary of all work completed

removed weed debris and stained soils and replaced tank sign