




## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 24, 2020 9:25:46 AM MST
Server Receive Date:	Jan 24, 2020 9:28:21 AM MST
Reference Number:	20200124-18130731260
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 24, 2020 9:27:49 AM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Jan 23, 2020
Well Name	TILLMAN BURCH GAS UNIT 2
API Number	50670863900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

after mowing



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

before mowing  
 removed weed debris from reclamation area



Additional photos



Completed work description  
Summary of all work completed

removed weed debris from reclamation area  
removed weed debris from reclamation area