

Pit Status Evaluation Form

Pit Overview:

| | |
|---|-------------------------------|
| Pit Name: B-1 MURRAY | Facility ID: 114643 |
| Current Status: Unknown | Status Date: 9/23/1999 |
| Current Operator: TXO PRODUCTION CORP / 90735 | |
| Updated Operator: | |
| Form 15 Pit Permit Doc #: | Permit Date: |
| Related Facilities: MURRAY B #1 (API 05-009-06131, Facility ID 205720 Loc ID 320995) | |

| | | | |
|--|-------------------|-------------------|-----------------|
| County: BACA | | | |
| Township: 32S | Range: 42W | Section: 5 | QQ: S2NE |
| Original Latitude/ Longitude: 37.290152 / -102.173569 | | | |
| Updated Latitude/ Longitude: / | | | |
| Basis for Location Change: | | | |

Pit Inspection/Information Request:

| | |
|---|--------------------|
| Field Inspection Date: | Document #: |
| Pit Still Present in Field: No | |
| Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below) | |
| Inspection Notes: | |
| Operator Required to Submit Form: NA | Due Date: |
| Form Request Sent To: | Sent Date: |

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565579 | Date: 10/9/1985 |
| | Doc #: 557383 | Date: 4/27/1998 |
| | Doc #: 200124184 | Date: 1/2/2008 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223928 | Date: 2/9/1998 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location. Well PA 7/28/2015

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document an open top fiberglass produced water tank on location. Related well was plugged 7/28/2015. Pit status has been changed to closed.