


6607BG11 299  
API: 05-103-11601  
Inspection: 679707128



**Photo 1. Location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

6607BG11 299  
API: 05-103-11601  
Inspection: 679707128



**Photo 2. Tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

6607BG11 299  
API: 05-103-11601  
Inspection: 679707128



**Photo 3. Separator.**

