

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402296249

Date Received:
01/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TESLA DOUGHERTY

9703045245

TESLA.DOUGHERTY@NBLENERGY.COM

KIMBERLY MOLLENHAUER

9703045307

KIMBERLY.MOLLENHAUER@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 699100928

Inspection Date: 01/21/2020

FIR Submit Date: 01/21/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 319269

Location Name: BARNETT-64N64W Number: 12NWSE County: WELD

Qtrqtr: NWSE Sec: 12 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.324130 Longitude: -104.495530

FACILITY - API Number: 05-123-00 Facility ID: 243186

Facility Name: BARNETT Number: 33-12

Qtrqtr: NWSE Sec: 12 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.324130 Longitude: -104.495530

CORRECTIVE ACTIONS:

1 ☒ CA# 136054

Corrective Action: "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 02/11/2020

Response: CA COMPLETED

Date of Completion: 01/27/2020

Operator Comment: NOBLE TREATED THE DIRT AND OILY WASTE AROUND THE WELLHEAD.
The contaminated soil around well head was cleaned up 01/27/2020 per Cogcc inspection.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 136055

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/11/2020

Response: CA COMPLETED

Date of Completion: 01/27/2020

Operator Comment: NOBLE CHECK ALL VALVES, PIPES, AND FITTINGS TO ENSURE THE WELLHEAD IS IN GOOD MECHANICAL CONDITION.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This location is turned in for a P&A and that should be done in the next 2 months.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: KIMBERLY MOLLENHAUER

Signed:

Title: EHS TECH

Date: 1/28/2020 11:34:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402296249	FIR RESOLUTION SUBMITTED
402296251	BARNETT 33-12 WELLHEAD
402296253	BARNETT 33-12 WELLHEAD

Total Attach: 3 Files