

**Well Name:** IGW 122      **API #** 05-067-09559  
FW Terrell Gas Unit 2      **API #** 05-067-07910  
**Inspection Number:** 6879036677  
**Corrective Action:** Oily rags and used parts on pumping unit skid.  
**Correction Action Due:** 2/11/2019  
**Action Completed:** 2/7/2019  
**Action Taken:** Removed oily rags and used parts

**Corrective Action:** Leaking valve and broken plug on IGW 122 production tank.  
**Correction Action Due:** 1/31/2018  
**Action Completed:** 2/7/2019  
**Action Taken:** Replaced leaking valve and installed steel bull plug.

**Corrective Action:** Tires in secondary containment  
**Correction Action Due:** 2/11/2019  
**Action Completed:** 2/4/2019  
**Action Taken:** Removed tires and trash from secondary containment.

