

Well Name: Harmon Gas Unit A 2 **API #** 05-067-07930
Well Name: IGE 141 **API #** 05-067-09901
Inspection Number: 687904515
Inspection Number: 687905075

Corrective Action: Repair secondary containment liner
Correction Action Due: 5/8/2019
Action Completed: 4/22/2019
Action Taken: Repaired tears in secondary containment liner

Correction Action Due:
Action Completed: 1/9/2020
Action Taken: Removed tank and secondary containment

