

Pit Status Evaluation Form

Pit Overview:

Pit Name: MAYBERRY 1	Facility ID: 114638
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 565645	Permit Date: 11/17/1971
Related Facilities: MAYBERRY #1 (API 05-009-06024, Facility ID 205613, Loc ID 378991)	

County: BACA			
Township: 34S	Range: 41W	Section: 10	QQ: NENW
Original Latitude/ Longitude: 37.103565 / -102.049664			
Updated Latitude/ Longitude: 37.103486 / -102.047645			
Basis for Location Change:			
Lat long updated based on aerial imagery			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 565645 | Date: 11/17/1971 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 565646 | Date: 5/22/1984 |
| Doc #: 565647 | Date: 12/3/1986 |
| Doc #: 200013337 | Date: 01/11/2001 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> COGIS Document – Doc #: 565648 | Date: 7/8/1985 |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 6/27/1985

Timing of Pit Closure:

Letter dated 7/8/1985 (doc #565648) documents that the pit was backfilled and replaced with a 210 bbl steel tank 6/27/1985. Well PA 6/7/2004.

Pit Status Review Summary:

The pit on location was closed and replaced by a steel tank 6/27/1985; associated well was plugged 6/7/2004. Pit status has been changed to closed.

